



Nu Flow re-lines home in Midrand

Location: Midrand, Gauteng


Situation: A leak detector was called to the house to find a leak that was causing damp in the walls of the home. The house was done with the composite pipes.

The home's insurance company had approved Nu Flow's epoxy lining to be used to re-line the pipes as re-tiling the house would be too expensive.

Solution: Mobile Leak Detection, a Nu Flow licensee used Nu Flow epoxy coating to re-line the entire bathroom's pipes working from existing access points.

After the pipes had been re-lined the damp problem stopped. The end result is a re-lined pipe repaired from the inside.

Are you concerned about elbows & tees in pipes?
Nu Flow re-lining process can effortlessly get around 90 degree bends!



How it Works

Step 1

The pipe is tested for leaks.

Step 2

An abrading agent is air blasted through the pipe to remove all rust and corrosion products.

Step 3

An epoxy mixture is then blasted through the pipe with conditioned air to uniformly distribute the epoxy lining throughout the pipe segment.

Result

The result is a relined pipe, repaired from the inside.
No damage to structures!
No chasing walls!
No digging!

Interested in Nu Flow pipe re-lining?
Want to become a Nu Flow installer?

0861 NU FLOW
0861 68 3569

info@nuflow.co.za
www.nuflow.co.za