



Nu Flow re-lines pipes at home in Meyersdal

Location: Meyersdal Eco Estate, Gauteng

Situation:

The home in Meyersdal Eco Estate was experiencing damp issues in one of the walls. This was caused by a full bore that had disjoined in two places allowing water to leak into the wall column of the main entrance hall.

The home owner did not want to chop open the column and cause structural damage to the beautiful home and then have to patch up the damage.

The home owner turned to Nu Flow for a better solution.

Are you concerned about elbows & tees in pipes?

Nu Flow re-lining process can effortlessly get around 90 degree bends!

From 15mm - 300mm
AC / Copper / PVC/HDPE / Earthenware / Galvanized

Solution:

Nu Flow used a pull-in-place structural liner to re-line the pipe working from existing access points and therefore caused absolutely NO damage to the structural integrity of the home.

Replacing the pipe would not only have taken weeks of work, but would result in damage to the building, noise, mess and rubble. The damage would need to be patched up afterwards and the walls re-plastered and re-painted.

Nu Flow were able to do the job in less than a day saving the client time and money.

No mess, no noise, no damage!

The end result is a new pipe with-in the original pipe.

**Interested in Nu Flow pipe re-lining?
Want to become a Nu Flow licensee?**

Contact us:

**0861 NU FLOW
0861 68 3569**

**info@nuflow.co.za
www.nuflow.co.za**