



## Morningside - Leaking Copper Pipes

**Location:** Morningside, Gauteng, South Africa

**Situation:** The home had leaking copper pipes running under a floor slab and with in the walls.

The homeowner did not want to chop open the floor slab and have the inconvenience of strangers inside the house for weeks chopping open, replacing the pipe and then patching up the damage, re-tiling and re-painting not to mention the dust, noise and rubble caused by this option. Instead the home owner turned to Nu Flow.

**Solution:** Nu Flow South Africa re-lined the copper pipes with an epoxy coating with out having to chop through the slab and walls.

The job took Nu Flow a fraction of the time that replacing the pipes would have taken. The end result is a re-lined pipe, repaired from the inside.

No Mess, no chopping open, no damage to structures!

**Interested in Nu Flow pipe re-lining?  
 Want to become a Nu Flow licensee?**

**Contact us:**

## How it Works

### Step 1

The pipe is tested for leaks.

### Step 2


An abrading agent is then air blasted through the pipe to remove all rust and corrosion products.

### Step 3

An epoxy mixture is then blasted through the pipe with conditioned air to uniformly distribute the epoxy lining through out the pipe segment.

### Result

The result is a **relined pipe**, repaired from the inside.  
 No damage to structures!  
 No chasing walls!  
 No digging!



From 15mm - 300mm

AC / Copper / PVC/HDPE / Earthenware / Galvanized