



## Nu Flow re-lines pipes at home in Sandhurst

**Location:** Empire rd, Sandhurst, Gauteng

**Situation:**

The home in Sandhurst was experiencing water damage in the roof slab above the lounge due to two leaking points in a PVC pipe running from one of the upstairs toilets.

The home owner called in a plumber who used a sealant to seal the two leaking points, but the problem continued.

The house has been tiled with very expensive tiles and as a result the home owner did not want to have to chop open the walls and floor to fix the leak. The home owner turned to Nu Flow instead.

From 15mm - 300mm

AC / Copper / PVC/HDPE / Earthenware / Galvanized

**Are you concerned about elbows & tees in pipes?**

Nu Flow re-lining process can effortlessly get around 90 degree bends!

**Solution:**

Nu Flow used a CCTV camera to locate and analyse the two leaking points in the pipe. Nu Flow then used a pull-in-place structural liner to re-line the pipe working from existing access points and therefore caused absolutely NO damage to the structural integrity of the home.

Nu Flow were able to do the job in less than a day saving the client time and money.

No mess, no noise, no damage!

The end result is a new pipe with-in the original pipe.

**Interested in Nu Flow pipe re-lining?  
Want to become a Nu Flow licensee?**

**Contact us:**