



## Atholl - Leaking Drain Pipe

**Location:** Atholl, Gauteng Province, South Africa

**Situation:**

The home had a 110mm PVC and earthenware drain pipe that was badly damaged which caused the pipe to experience continual blockages. The drain pipe ran under the house and replacing the pipe would mean chopping open the kitchen floor and beautifully landscaped garden at an estimated cost of R100,000.00

**Solution:**

Nu Flow South Africa used pull in place structural liners to re-line the damaged pipe a without having to break through the kitchen floor and garden.

The residents of the house were able to continue with their daily activities while the pipe was being relined.

No damage to structures, no mess, no disturbance!

The end result is a new pipe with in the old pipe.

For more information on Nu Flow pipe relining or on becoming a Nu Flow licensee please contact us



(+27) 11 425 3379

[www.nuflow.co.za](http://www.nuflow.co.za)

[info@saleak.co.za](mailto:info@saleak.co.za)

