



Blue Hills Country Estate - Leaking Drain Stacks

Location: Blue Hills Country Estate, Gauteng Province, South Africa

Situation:

The home had three 100mm PVC drain stacks that were leaking due to nails been hammered into the wall columns which punctured the pipes. The leaking pipes caused major water damage to both the inside and outside walls of the house.

Solution:

Nu Flow South Africa used structural liners to reline the leaking pipe with out having to break through the wall columns or beautifully tiled bathroom wall and floors despite the pipe containing 90° bends.

The residents of the house were able to continue with their daily activities while the pipes were being relined. The end result is a new pipe with in the old pipe

For more information on Nu Flow pipe relining or on becoming a Nu Flow licensee please contact us



Before



After