

Customer:

Ferrari Store,
William Nicol Drive

Situation:

2 fullbores and a
160mm cast iron
storm water pipe
within a column which
were leaking.

Contractors had placed
bolts in the column, one of
which had punctured the
down pipe.

Replacing the pipe was not
possible since it runs within a
structural column.

Solution:

Nu Flow lined the 2 full bores and the
down pipe working from the full bore
and floor drain as access points.



Ferrari



NU FLOW™
RELINE REPAIR RENEW

SOUTH AFRICA

Contact us for more information.

Head office / Training centre

Plot 13

Road Number 5

Brentwood Park

Benoni

Telephone: 087 160 0330

Email: enquiries@nuflow.co.za

Website: www.nuflow.co.za

No Mess! No Damage! No chopping open!