



Nu Flow re-lines full bore in Mountain Rise

Location: Mountain Rise, Pietermaritzburg, KZN

Situation:

The home in Mountain Rise was experiencing water damage from a 110mm PVC full bore that was leaking every time it rained. The pipe ran with in a wall column in the lounge.

An inspection and further investigation revealed that a technician had drilled into the column and through the pipe while installing a data cable leaving a 10mm hole through the pipe.

A contractor sealed the hole with silicon, but this solution did not work. Mountain Rise turned to Nu Flow for a permanent solution.

Solution:

Ganga Plumbers, a Nu Flow licensee, re-lined the pipe with Nu flows pull-in-place structural liner system working from existing access points thereby causing no disruption or structural damage to the building.

The end result is a new pipe with in the old pipe. No Mess, no chopping open, no damage to structures!

Are you concerned about elbows & tees in pipes?

Nu Flow re-lining process can effortlessly get around 90 degree bends!

**Interested in Nu Flow pipe re-lining?
Want to become a Nu Flow licensee?**

Contact us:

**0861 NU FLOW
0861 68 3569**

**info@nuflow.co.za
www.nuflow.co.za**