



## Sun City Palace - Cheetah Fountain

**Location:** Sun City Palace, North West Province

### Situation:

What sort of first impression would it be to arrive at the beautiful Sun City Palace only to be greeted by an excavated entrance to the palace due to leaks in the Cheetah fountains pipes.

When Sun City found the Cheetah fountain leaking, excavation was not an option. Sun City turned to Nu Flow for a solution.

### Solution:

Nu Flow South Africa reviewed, diagnosed and repaired broken pipes on the Cheetah fountain with the Nu Flow structural lining system.

Nu Flow did the diagnostics and repair during Sun City's routine maintenance schedule working from existing access points with out causing any damage to the fountain and surrounding paving.

**Interested in Nu Flow pipe re-lining?  
Want to become a Nu Flow installer?**

**Contact us:**

(+27) 11 425 3379  
[www.nuflow.co.za](http://www.nuflow.co.za)  
[info@saleak.co.za](mailto:info@saleak.co.za)

