



Leaking Pipes?
Why re-pipe?
Toyota didn't!

Nu Flow relines at Toyota Factory

Location: Durban, KwaZulu-Natal

Situation:

Toyota Prospecion Manufacturing Plant had a 160mm earthenware sewer pipe that was continuously blocking due to multiple cracks and shifted joints along the 266 meter line.

The pipe runs five meters below surfaces.

Excavating a five meter deep trench in order to replace the 266 meters of pipe would take weeks, causing major disruptions to the production plants 24 hour operations.

This was not an option for Toyota. Instead they turned to Nu Flow for a better solution.

Solution:

Ganga Plumbers, a Nu Flow licensee, relined the failing pipe with Nu Flow's pull-in-place structural liner system working from existing access points, thereby causing no disruption to Toyota's 24 hour operations.

The end result is a new pipe within the old pipe. No damage, no excavation, no mess!

Are you concerned about elbows & tees in pipes?

Nu Flow can reline 90 degree bends & tees effortlessly!

From 15mm - 300mm

AC / Copper / PVC / HDPE Earthenware / Galvanized

Need relining done?
Want to become a Nu Flow Installer?

Contact us:

0861 NU FLOW
info@nuflow.co.za
www.nuflow.co.za



Turn this...

...into this!